

Auxiliary material for switch, TB, 10°/U88, asymmetric turnout left/right hand

Item number 100869



Comments

- This auxiliary material included in the complete installations (superassemblies)

- Without fixed terminations for grooved contact wire, supporting network and suspension
- The exact individual parts-list can be seen in the respective installations plans