

# Auxiliary material for switch, TB, 10° asymmetric, U99

Item number 100214



## Comments

- This auxiliary material included in the complete installations (superassemblies)

- Without fixed terminations for grooved contact wire, supporting network and suspension

- The exact individual parts-list can be seen in the respective installations plans